



Facilities Report November 2025



- Lower elementary had a leak spring in the ceiling earlier in the month, galvanized pipes are rusting from the inside out. A year or so ago had another leak happen on the same line and with the corrosion there will be more. Also, most of the drain pipes in the elementary are cast iron which is having a similar fate of rusting on the inside however, the scale that builds up creates trapping of things flushed and have been having issues with backups.
- Winterized football concessions/ press box, I tested water before blowing out the pipes and had another coliform positive test. When I put together and turn the water back on in the spring I will meet with the health department and try to once again try to figure out the cause since it's been a recent phenomenon in the last couple of years. One way to alleviate having to test would be to put the domestic water for the outside buildings would be to tie it into the village water supply which would be tested before we receive it and would not have to do testing and have the well chlorinated repeatedly.
- Working on getting estimates to make some improvements to the GSRP room with their provided funding.